AISIBLE FIMISSION NOTATIONS			mary .		
Inspector:	+		_		
Date of Inspection: 9/,//5					
Shift: (1st Shift or 2nd Shift	t Time:	304		·	
Unit:	Misvai Inspertition I <u>NORIMAL</u> OI <u>ABNORIMAL</u>		Con	nimenis	
Visible Emission From Shaker	No-				
Visible Emission From Discharge Conveyor System	Nor				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

AIZIBLE EMIZZION NOTATIONZ			_		
Inspector:	at-				
Date of Inspection: 9/2/15	0				,
Shift: (1st Shift or 2nd Shift	t Time:	3 fm			
Unit	Wisual)		Con	dinenis	
	<u>INIORIMIAL</u>				
	ABNORMAL				
Visible Emission From Shaker	Nov				
Visible Emission From Discharge					
Conveyor System	Non	And the second s	MICELLY NAME AND ADDRESS OF THE PARTY OF THE		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

AISIBLE EMISSION MOTATIONS			_		
Inspector:	C-5/~				
Date of Inspection: $9/3/$	15				
Shift: (1st)Shift or 2nd Shift	Time:	3PM			
Unit	Visual Inspection <u>NORMAL</u> Or ABNORMAL			mments	
Visible Emission From Shaker	No	egs der Misselle Flack-offen soller Misselle George oder eine Zustalle der George oder eine Zustalle der Stelle	1 ² enne general gener		
Visible Emission From Discharge Conveyor System	Nov		Frank McCOP Residence College		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS			-		
Inspector:	sot on				
Date of Inspection: 9/4/15	<i>-</i>				•
Shift: 1st Shift or 2nd Shift	Time:	18M			
Unit	Visual		. Com	iments	
	<u>NORMAL</u>				
	<u>ABNORMAL</u>				
Visible Emission From Shaker	Nor	*** THE RECOVERING AND COMPANY AND			
Visible Emission From D ischarge Conveyor System	· A)		Million and the second		
Conveyor system	100/				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS			pri		
Inspector:	'Capta		_		
Date of Inspection: 9/5//3	> 0				•
Shift: 1st Shift or 2nd Shift	Time:	1Pm			
Unit	, Wisylai Inseredion		Co	nilinGelGS	
	<u>MORIMAL</u>				
	ABNORMAL T				
Visible Emission From Shaker	Nov				
Visible Emission From Discharge					
Conveyor System	Nor		25.		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS						
Inspector:	C _ +					
Date of Inspection: 9/6/	1,50				•	
Shift: 1st Shift or 2nd Shift	t Time:	18 M				
Uniti	Misvali linspeditoni Monwali			20 minienes		
	OJ ABNIORIMAL					
Visible Emission From Shaker	No-	gan operation the company of the com	odiasa-ilkalisalitan, alkasi-en yelesayan an yelesayan an yelesayan a			
Visible Emission From Discharge Conveyor System	1	and the state of t	collection of the first of the second of the			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

AISIBLE EMISSION NOTATIONS			mar.		
Inspector:	of to				
Date of Inspection: $9/7/\sqrt{5}$	-0			•	
Shift: 1st Shift or 2nd Shift	t Time:	1807			
. Waite _	Misual Linspesition		Comina	enis	
	INORMIAL OF ABNORMAL				
Visible Emission From Shaker	Nor	Printing the squared and property of the state of the sta	Section and the section of the secti		Anna de la companya d
Visible Emission From Discharge Conveyor System	Not	, in particular distribution and the place of the place o			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EIVIISSION NOTATIONS			_		
Inspector: Ted Cal	t				
Date of Inspection: 9/8/15					
Shift: 1st Shift or 2nd Shift	Time:	2007			
Unit	Visual Inspection <u>Normal</u> or		G	guimenis	
Visible Emission From Shaker	No /				
Visible Emission From Discharge Conveyor System	No	C 20 collection and the Participation of the State of the			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

Inspector:	ant an			
Date of Inspection: 9/9/15	-0			
Shift: (1st Shift or 2nd Shift	Time:	28M		
Unit:	Wistell or		Comment	
	<u>MORAMVAL</u> og			
	<u>ABNORMAL</u> (1)			
Visible Emission From Shaker	Nor	- And the second	~	
Visible Emission From Discharge	. 4 1			
Conveyor System	Nor	Allowania and the second and the sec		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS					
Inspector:	pton				
Date of Inspection:	19/10/15				•
Shift: 1st Shift or 2nd Shift	Time:	3 <i>8</i> m			
Unit	Visual Inspection		Go	mments	
	<u>IMORIANI</u> To IMAMINGININEN				
Visible Emission From Shaker	No.		123-25-26 (19-25-25-25-25-25-25-25-25-25-25-25-25-25-	A THE PARTY OF A DAY BEFORE SHEET WORLD IN THE PARTY OF THE PARTY.	
Visible Emission From Discharge Conveyor System	Not				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

AISIBLE EMISSION NOTATIONS			=		
Inspector:	1 Capta	-			
Date of Inspection: 9/11/15					
Shift: 1st Shift or 2nd Shift	Time:	200			
Uniti	Vilsuali Jinspedikon		Colin	រណ៍មិស្រី	
	MORIMAL				
	ABNORMAL				
Visible Emission From Shaker	No				·
Visible Emission From Discharge					
Conveyor System			1900 mills of Grande Amelion and Amelion a		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

AISIBLE FIMISSION MOTATIONS		المراقعة والمراقعة والمراقعة والمراقعة والمراقعة والمراقعة والمراقعة والمراقعة والمراقعة والمراقعة	-1		
	enstan		_	·	
Date of Inspection: 9/12/15	-U				•
Shift: 1st Shift or 2nd Shift	Time:	1807			
Uniti	Visual		Con	imenis	
	<u>INIORIMIAL</u>				
	ABNORIMAL				
Visible Emission From Shaker	No	#2mmontorpreguents (1999-1997) in the final behavior of the final			
Visible Emission From Discharge	4				
Conveyor System	I No				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS			•		
Inspector: Ted Call	1				
Date of Inspection: 9/13/15					•
Shift: 1st Shift or 2nd Shift	Time:	12 PM			
Unit	Mistal Inspection <u>NORMAL</u>		Con	nimienas	
Visible Emission From Shaker	O)				
Visible Emission From Shaker	Nor				
Visible Emission From Discharge Conveyor System	Nar		National State Control of Control		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

Inspector:	int -				
Date of Inspection:	0				
Shift: 1st)Shift or 2nd Shift	Time:	9 A M			
Unit s. tr.	Visual Inspection NORMAL OF ABNORMAL		Cor 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	niments	
Visible Emission From Shaker	No		-		
Visible Emission From Discharge Conveyor System	Na				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

Inspector:	1 agt			
Date of Inspection:	<i>/ </i>			
Shift: 1st Shift or 2nd Shift	t Time:	10 AW		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	No	фенциализмичной менционализмической под предоставления и под предоставления и под под предоставления под предоставления под	ggengen -	
Visible Emission From Discharge Conveyor System	N.	Grant was the shall fill the district of the state of t	and the second s	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

Inspector:	d Cata			
Date of Inspection: 9/16/15	Ü			
Shift: 1st Shift or 2nd Shif	t Time:	10 Avg		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	No	A COMPA CONTROL ACCOUNT OF A C	age And Michigan Communication	
Visible Emission From Discharge Conveyor System	Na			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

Inspector:	An			
Date of Inspection:	<u></u>		-	
Shift: 1st Shift or 2nd Shif	t Time:	10 AM		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	N.	go and the second secon	towing/INP**	
Visible Emission From Discharge Conveyor System	No	Extractitional regulation of the security of t	olike didinankaming ngapulangan tari	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

Inspector:	1 C-t-		
Date of Inspection:			
Shift: 1st Shift or 2nd Shift	Time:	UAN	
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments
Visible Emission From Shaker	Nor		sentim plate for consiste all the first of t
Visible Emission From Discharge Conveyor System	N.		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS			
Inspector:	127-		
Date of Inspection:			
Shift: 1st Shift or 2nd Shift	Time:	16M	
Unit	Visual		Comments
	Inspection		
	<u>NORMAL</u>		
	or		
	<u>ABNORMAL</u>		
Visible Emission From Shaker	No	- Security and a security of the security of t	
Visible Emission From Discharge			
Conveyor System	$\Lambda I -$	And the second s	The state of the s

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS				
Inspector:	-dC-At	The committee of the contract		
Date of Inspection:	1,5			
Shift: 1st Shift or 2nd Shift	Time:	3 PM		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	No-	The state of the s	### <u>##################################</u>	
Visible Emission From Discharge Conveyor System	No	propries and the second	Annia an	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

Inspector:	edland	Manifest -	
Date of Inspection:	1/15		
Shift: 1st shift or 2nd Shift	t Time:	11 AN	
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments
Visible Emission From Shaker	Nor	A MARKAN THE COLUMN TO THE COLUMN	
Visible Emission From Discharge Conveyor System	N.	Consumer and an artist and an artist and artist	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS Inspector: Date of Inspection: Time: Shift: 1st \$hift 2nd Shift 9 AN Unit Visual Comments Inspection NORMAL or **ABNORMAL** Visible Emission From Shaker Visible Emission From Discharge Conveyor System

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS				
Inspector: $\frac{1}{1} \in \mathcal{O}($	1			
Date of Inspection: 9/23/	15			
Shift: 1st Shift or 2nd Shift	t Time:	10 AV1		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	Not		THE COLUMN TO A STATE OF THE COLUMN TO A STATE	
Visible Emission From Discharge Conveyor System	Nec	Contraction of the state of the	and the second s	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS Inspector: Date of Inspection: Shift: 1st shift or 2nd Shift Time: Unit Visual Comments Inspection NORMAL or ABNORMAL

Normal means emissions prevailing or expected to prevail 80% of time process in operation, not counting start up ro shut down

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

Visible Emission From Shaker

Conveyor System

Visible Emission From Discharge

VISIBLE EMISSION NOTATIONS	/		
Inspector:	of and		
Date of Inspection: 9/25/15			
Shift: 1st shift or 2nd Shift	Time:	8:30 AW7	
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments
Visible Emission From Shaker	No-	_constitution receptor (which the constitution of the constitution	
Visible Emission From Discharge Conveyor System	Non	gent spark gent til finde skattere kant skatt skat	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

MICIDIE ENAICCIONI NIOTATIONIC

VISIBLE EIVIISSION NOTATIONS		<u> </u>		
Inspector:	ed Carta	N. Augustanian		
Date of Inspection: 9/26/	15			
Shift: 1st Shift or 2nd Shift	t Time:	2 Pm	•	
Unit	Visual		Comments	
	Inspection			
	NORMAL			
	or			
	<u>ABNORMAL</u>			
Visible Emission From Shaker	No			
Visible Emission From Discharge				
Conveyor System	1	, at a month, response of the contract of the		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS	1			
Inspector: Ted Capture				
Date of Inspection: 9/27 /15				
Shift: 1st Shift or 2nd Shift	Time:	30M		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	N, -			
Visible Emission From Discharge Conveyor System	Nov			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

Inspector:) ingo in on			
Date of Inspection: $9/28/75$				
Shift: 1st shift or 2nd Shift	t Time:	9400		
Unit	Visual Inspection <u>NORMAL</u> or ABNORMAL		Comments	
Visible Emission From Shaker	No	All and the second of the seco		<u> </u>
Visible Emission From Discharge Conveyor System	Nor	gen and the management distributed parameters are supplied to the supplied of		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS			
Inspector: R L	bve		
Date of Inspection: 9/29	115		
Shift: 1st Shift or 2nd Shift	Time:	9 Am	
Unit	Visual Inspection <u>NORMAL</u> or ABNORMAL		Comments
Visible Emission From Shaker	NOR		
Visible Emission From Discharge Conveyor System	NOR		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS				
Inspector: R Long				
Date of Inspection: 9/30/	15			
Shift: 1st Shift or 2nd Shif	t Time:	9 Am		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	Nor			
Visible Emission From Discharge Conveyor System	Nor			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)